

| Title: | Carpentry Level One | | | | | | | |
|------------------------------------|---|--------------|-------------------------------|------------------|---------------|--------------------|--|---------------------------------|
| Edition: | 1st | | | | | | | |
| Pub Date: | 2008 | | | | | | | |
| Addl. Instructor Require.: | Bi-lingual (English/Spanish), Journey-level Carpenter | | | | | | | |
| Prerequisite: | Core (Spanish) | | | | | | | |
| Previous Edition Exp. Date: | | | | | | | | |
| Book Module # | Old Mod ID # | New Mod ID # | Equivalent Registry Module(s) | Performance Test | Current Hours | New Hours | Mod Name | Comments |
| | | | | | | 72.5 | Core Curricula Modules | See Core (Spanish) revision map |
| 1 | | ES27101-06 | 27101-06 | No | | 2.5 | Orientation to the Trade (Spanish) | |
| 2 | | ES27102-06 | 27102-06 | Yes | | 7.5 | Building Materials, Fasteners and Adhesives (Spanish) | |
| 3 | | ES27103-06 | 27103-06 | Yes | | 10 | Hand and Power Tools (Spanish) | |
| 4 | | ES27104-06 | 27104-06 | Yes | | 20 | Reading Plans and Elevations (Spanish) | |
| 5 | | ES27105-06 | 27105-06 | Yes | | 25 | Floor Systems (Spanish) | |
| 6 | | ES27106-06 | 27106-06 | Yes | | 20 | Wall and Ceiling Framing (Spanish) | |
| 7 | | ES27107-06 | 27107-06 | Yes | | 37.5 | Roof Framing (Spanish) | |
| 8 | | ES27108-06 | 27108-06 | Yes | | 5 | Introduction to Concrete and Reinforcing Materials (Spanish) | |
| 9 | | ES27109-06 | 27109-06 | Yes | | 12.5 | Windows and Exterior Doors (Spanish) | |
| 10 | | ES27110-06 | 27110-06 | Yes | | 12.5 | Basic Stair Layout | |
| | | | | | | Total Hours | 225 | |

Color Highlight Legend

| | | | |
|---|--------------------|---|-----------------------|
|  | = Lock-Down Module |  | = No Performance Test |
|  | = New Module |  | = Equivalent Module |
| | |  | = Deleted |
| | |  | = Interim Credential |

Definitions:

Lock-Down Module: A module adopted 'as is' from another craft or an earlier edition of the same curriculum.

Equivalent Module: A module whose learning and performance outcomes match those of the newer edition's and is therefore considered 'equivalent' in NCCER's Registry

| Title: | Carpentry Level Three | | | | | | | |
|------------------------------------|---|--------------|-------------------------------|------------------|--------------------|--------------|---|----------|
| Edition: | 1st | | | | | | | |
| Pub Date: | 2010 | | | | | | | |
| Addl. Instructor Require.: | Bi-lingual (English/Spanish), Journey-level Carpenter | | | | | | | |
| Prerequisite: | | | | | | | | |
| Previous Edition Exp. Date: | | | | | | | | |
| Book Module # | Old Mod ID # | New Mod ID # | Equivalent Registry Module(s) | Performance Test | Current Hours | New Hours | Mod Name | Comments |
| 1 | | ES27301-07 | 27301-07 | No | | 10 | Rigging Equipment (Spanish) | |
| 2 | | ES27302-07 | 27302-07 | Yes | | 15 | Rigging Practices (Spanish) | |
| 3 | | ES27303-07 | 27303-07 | Yes | | 10 | Properties of Concrete (Spanish) | |
| 4 | | ES27304-07 | 27304-07 | Yes | | 15 | Reinforcing Concrete (Spanish) | |
| 5 | | ES27305-07 | 27305-07 | Yes | | 22.5 | Handling and Placing Concrete (Spanish) | |
| 6 | | ES27306-07 | 27306-07 | Yes | | 10 | Trenching and Excavating (Spanish) | |
| 7 | | ES27307-07 | 27307-07 | Yes | | 20 | Foundations and Slab-on-Grade (Spanish) | |
| 8 | | ES27308-07 | 27308-07 | Yes | | 27.5 | Vertical Formwork (Spanish) | |
| 9 | | ES27309-07 | 27309-07 | Yes | | 22.5 | Horizontal Formwork (Spanish) | |
| 10 | | ES27310-07 | 27310-07 | Yes | | 20 | Tilt-Up Wall Panels (Spanish) | |
| | | | | | Total Hours | 172.5 | | |

Color Highlight Legend

| | | | |
|---|--------------------|---|-----------------------|
|  | = Lock-Down Module |  | = No Performance Test |
|  | = New Module |  | = Equivalent Module |
| | |  | = Deleted |
| | |  | = Interim Credential |

Definitions:

Lock-Down Module: A module adopted 'as is' from another craft or an earlier edition of the same curriculum.

Equivalent Module: A module whose learning and performance outcomes match those of the newer edition's and is therefore considered 'equivalent' in NCCER's Registry